

| ID          | Model and Option                            | Replacement product | Modification or comments   |
|-------------|---|---------------------|--|
| 0202-100014 | //B-SC-CF-P12-P21-O-L-U-NE                  | 3-72-7079           | Board not available separatly  |
| 0202-100022 | B-SC-MP-P12-P21-O-L-IR-U-CC5                | 3-72-7079           | IR sensor not compatible anymore, board not available separatly  |
| 0202-100023 | B-SC-MP-P12-P22-B-O-CP-L-EE- T2-NW-HQ6      | not replaceable     | See HQ for replacement   |
| 0202-100036 | B-SC-MP-P12-P21-B-O-CP-L-EE-NW-U-HQ6        | not replaceable     | See HQ for replacement   |
| 0202-100038 | B-SC-MP-P12-P2-B-O-L-U-FB-JJC-NE-SBD        | 0202-205162         | Board not available separatly  |
| 0202-205001 | SSPA-1-P122-O1-NE-LS-H4.0-JJC-RL            | 0202-205212         | No plugs on the pack anymore   |
| 0202-205002 | **SSPA-1-P122-P212-O1-LS-H5.5-JJM-RL        | 3-72-7079           |  |
|             |   |                     | Overlay will have to be changed if single pump system: TSC-9, 9916-100186: TSC-18, 9916-100240: TSC-19, 9916-100219 / Pump 1 always dual speed / Jumper setting different / Fonctionnalities different |
| 0202-205003 | **SSPA-1-P112-B2-O1-CP2-LS-JJM-AX           | 0202-205162         |  |
| 0202-205004 | **SSPA-1-P122-P212-O1-LS-H5.5-AMP           | 3-72-7078           |  |
| 0202-205005 | **SSPA-1-P121-B1-O1-LS-H5.5-AMP             | 3-72-7078           |  |
| 0202-205006 | SSPA-1-P121-O1-LS-H4.0-AMP                  | 0202-205212         | No plugs on the pack anymore   |
| 0202-205007 | **SSPA-1-P122-O1-LS-H5.5-AMP                | 0202-205212         | No plugs on the pack anymore   |
| 0202-205008 | **SSPA-1-P122-B2-O1-LS-H5.5-JJM-AL          | 3-72-7079           |  |
| 0202-205009 | **SSPA-1-P122-O1-NE-LS-H5.5-JJM-RL-AL       | 0202-205212         | No plugs on the pack anymore   |
| 0202-205010 | **SSPA-1-P122-P212-O1-LS-H4.0-AMP-MQ        | 3-72-7078           |  |
| 0202-205011 | **SSPA-1-P122-P212-O1-LS-JJM-RL             | 3-72-7079           |  |
| 0202-205012 | **SSPA-1-P122-B2-O2-NE-LS-H5.5-AMP-RL-SB    | 3-72-7078           |  |
| 0202-205013 | **SSPA-1-P122-B1-O1-LS-JJM                  | 3-72-7079           |  |
| 0202-205014 | **SSPA-1-P122-O1-LS-H4.0-AMP-ND             | 0202-205212         | No plugs on the pack anymore   |
| 0202-205015 | **SSPA-1-P122-B1-O1-LS-H5.5-JJM-RL          | 3-72-7079           |  |
| 0202-205016 | **SSPA-1-P121-NE-LS-H1.0-WK                 | 0202-205212         | If keypad with a special shape, will have to change the keypad for a 0202-007002. If a TSC-9, change the overlay for a 9916-100131 / Fonctionnalities different  |
| 0202-205017 | **SSPA-1-P122-P212-O1-LS-H4.0-D1            | 3-72-7079           | If single pump system, change the overlay for a 9916-100131 / If dual pump system, change the overlay for a 9916-100186 / Auxiliary switch not compatible anymore                                      |
| 0202-205018 | //SSPA-1-P122-B2-O1-NE-LS-H5.5-JJM-RL-AL    | 3-72-7079           |  |
| 0202-205019 | **SSPA-1-P121-O1-LS-H1.0-AMP-GFCI-AP        | 0202-205212         | No plugs on the pack anymore   |
| 0202-205021 | **SSPA-1-P112-O1-CP2-LS-JJM-AX3             | 0202-205212         | Jumper setting different / Fonctionnalities different / No plugs on the pack anymore   |
| 0202-205023 | **SSPA-1-P121-O1-LS-AMP                     | 0202-205212         | No plugs on the pack anymore   |
| 0202-205025 | **SSPA-1-P121-B1-O1-LS-AMP                  | 3-72-7078           |  |
| 0202-205026 | SSPA-1-P122-B2-O1-CP2-LS-JJC-AX6            | 0202-205162         | Overlay will have to be changed if single pump system: TSC-9, 9916-100186: TSC-18, 9916-100240: TSC-19, 9916-100219 / Pump 1 always dual speed / Jumper setting different / Fonctionnalities different |
| 0202-205027 | **SSPA-MP-P122-P212-O1-NE-LS-FB-JJM-LA      | 3-72-7079           | No FB output / Will need to change the overlay, no more ozone icon: 1 pump system 9916-100218; 2 pumps system 9916-100219; 1 pump + blower 9916-100219   |
| 0202-205028 | **SSPA-1-P122-P212-B1-O1-LS-JJM-LA2         | 0202-205162         | Pump 2 alway single speed / No more ozone icon on keypad. Overlay will have to be changed : 9916-100219 / Jumper setting different / Fonctionnalities different  |
| 0202-205029 | **SSPA-1-P122-B1-O1-LS-H5.5-AMP             | 3-72-7078           |  |
| 0202-205030 | **SSPA-1-P122-B1-O1-LS-AMP                  | 3-72-7078           |  |
| 0202-205031 | **SSPA-1-P122-P212-O1-LS-JJM                | 3-72-7079           |  |
| 0202-205032 | **SSPA-1-P122-P212-O1-CP1-LS-NE-JJM-MA1     | 0202-205162         | Pump 1 always dual speed / Overlay will have to be changed if single pump system: TSC-9, 9916-100186: TSC-18, 9916-100240: TSC-19, 9916-100219 / Jumper setting different / Fonctionnalities different |
| 0202-205033 | **SSPA-1-P121-O1-LS-JJM                     | 0202-205212         | No plugs on the pack anymore   |
| 0202-205034 | **SSPA-1-P122-P212-O1-NE-LS-H5.5-JJM-RL-CC2 | 3-72-7079           |  |
| 0202-205035 | **SSPA-1-P122-O1-NE-LS-H5.5-JJM-RL-CC       | 0202-205212         | No plugs on the pack anymore   |
| 0202-205037 | **SSPA-1-P122-O1-CP2-LS-JJM-AX7             | 0202-205212         | Jumper setting different / Fonctionnalities different / No plugs on the pack anymore   |
| 0202-205038 | **SSPA-1-P122-B1-O1-NE-LS-JJM-MG1           | 3-72-7079           | No more standby mode / Fonctionnalities different  |
| 0202-205040 | **SSPA-1-P122-B1-O1-NE-LS-H5.5-JJM-SU1      | 3-72-7079           |  |
| 0202-205041 | **SSPA-1-P122-P212-B1-O1-LS-H5.5-AMP-HY1    | 0202-205163         | Jumper setting different / Lock mode added / Temperature unit option added / Fonctionnalities different  |
| 0202-205042 | **SSPA-1-P122-B2-O1-LS-H5.5-AMP             | 3-72-7078           |  |
| 0202-205043 | **SSPA-1-P122-B2-O1-LS-H5.5-JJM             | 3-72-7079           |  |

|             |  |                 |   |
|-------------|--|-----------------|---|
| 0202-205044 | **SSPA-1-P122-B2-O2-LS-H5.5-AMP                  | 3-72-7078       |   |
| 0202-205045 | **SSPA-1-P122-P212-O1-LS-H5.5-JJM                | 3-72-7079       |   |
| 0202-205046 | **SSPA-1-P121-B1-O1-LS-H5.5-AMP-DK               | 3-72-7078       |   |
| 0202-205047 | **SSPA-1-P122-O1-LS-H5.5-JJM                     | 0202-205212     | No plugs on the pack anymore  |
| 0202-205048 | **SSPA-1-P122-P212-B1-O2-NE-LS-H5.5-AMP-HS       | 0202-205163     | Jumper setting different / Lock mode added / Temperature unit option added / Fonctionnalités different  |
| 0202-205049 | **SSPA-1-P122-O1-LS-H5.5-AMP-SL                  | 0202-205212     | No plugs on the pack anymore  |
| 0202-205050 | **SSPA-1-P121-O1-NE-LS-H5.5-AMP-DK               | 0202-205212     | No plugs on the pack anymore  |
| 0202-205051 | **SSPA-MP-P122-O1-NE-LS-AMP-ND2                  | 0202-205212     | No plugs on the pack anymore  |
| 0202-205052 | **SSPA-1-P122-O1-NE-LS-H5.5-AMP-HY1              | 0202-205212     | No plugs on the pack anymore  |
| 0202-205053 | **SSPA-1-P122-B2-O2-LS-H5.5-AMP-T2               | 3-72-7078       | Replace transformer by a 560AA0430  |
| 0202-205055 | **SSPA-1-P121-NE-LS-WK                           | 0202-205212     | If keypad with a special shape, will have to change the keypad for a 0202-007002. If a TSC-9, change the overlay for a 9916-100131. Fonctionnalités different   |
| 0202-205056 | **SSPA-MP-P122-P212-B1-O1-NE-LS-FB1-JJM-MA1      | 0202-205162     | Jumpers different / Lock mode added / Fonctionnalités different   |
| 0202-205057 | **SSPA-MP-P122-P212-O1-CP1-LS-H4.0-JJM-D12       | Not replaceable | See D1 for replacement  |
| 0202-205059 | **SSPA-1-P122-B1-O1-NE-LS-H5.5-AMP-SL            | 3-72-7078       |   |
| 0202-205060 | **SSPA-1-P121-O1-LS-H5.5-JJM                     | 0202-205212     | No plugs on the pack anymore  |
| 0202-205061 | SSPA-1-P122-O1-NE-LS-H5.5-AMP-OM                 | 0202-205212     | No plugs on the pack anymore  |
| 0202-205062 | SSPA-1-P122-P212-O1-NE-LS-FB-H5.5-AMP-OM1        | 3-72-7078       |   |
| 0202-205063 | **SSPA-MP-P122-P212-B1-O1-NE-L2S-H5.5-AMP-HY2    | 0202-205163     | Jumper setting different / Lock mode added / Temperature unit option added / Single switches not supported / Fonctionnalités different  |
| 0202-205064 | **SSPA-1-P122-P212-O1-LS-H4.0-AMP                | 3-72-7078       |   |
| 0202-205066 | **SSPA-1-P121-LS-JJM-RL                          | 0202-205212     | No plugs on the pack anymore  |
| 0202-205067 | **SSPA-MP-P122-P212-B1-O1-NE-LS-FB1-JJM-LA3      | 0202-205162     | Jumper setting different / Pump 2 only single speed / Lock mode added / Fonctionnalités different   |
| 0202-205068 | **SSPA-MP-P122-P212-O1-CP1-NE-L2S-AMP-HY3        | 0202-205209     | Comes with JJM plugs only, so will need to re-use the Amp plugs from the old pack / Will need to change the keypad, if single pump system: 0202-007103, if dual pump system: 0202-007104 / Auxiliary switches not supported anymore / Fonctionnalités different / Jumper setting different  |
| 0202-205069 | **SSPA-1-P121-O1-NE-LS-FB-H5.5-AMP-GP2           | 3-72-7078       | If the pack is changed, the overlay will need to be changed because of the ozone led TSC-18 9916-100240 / No FB output  |
| 0202-205070 | **SSPA-1-P122-B2-O2-NE-LS-HP-AMP-AP2             | 0202-205209     | Comes with JJM plugs only, so will need to re-use the Amp plugs from the old pack / Pump 2 always enabled, so if using a single pump will need to change the overlay: TSC-9: 9916-100186 ; TSC-18: 9916-100240 ; TSC-19: 9916-100219 / Fonctionnalités different / Jumper setting different |
| 0202-205071 | **SSPA-1-P122-O1-NE-LS-HP-AMP-AP2                | 0202-205209     | Comes with JJM plugs only, so will need to re-use the Amp plugs from the old pack / Pump 2 always enabled, so if using a single pump will need to change the overlay: TSC-9: 9916-100186 ; TSC-18: 9916-100240 ; TSC-19: 9916-100219 / Fonctionnalités different / Jumper setting different |
| 0202-205072 | **SSPA-1-P121-O1-NE-LS-HP-GFCI-AMP-AP2           | 0202-205209     | Comes with JJM plugs only, so will need to re-use the Amp plugs from the old pack / Pump 2 always enabled, so if using a single pump will need to change the overlay: TSC-9: 9916-100186 ; TSC-18: 9916-100240 ; TSC-19: 9916-100219 / Fonctionnalités different / Jumper setting different |
| 0202-205073 | SSPA-1-P122-O1-LS-H4.0-JJC                       | 0202-205212     | No plugs on the pack anymore  |
| 0202-205077 | **SSPA-1-P121-O1-NE-LS-H1.0-RL-JJM-WK2           | 0202-205212     | Will need to change the overlay(9916-100131) / no more display disabling(jumper 3) / no more tranquill mode / Different way of programming filtration cycle / Fonctionnalités different / No plugs on the pack anymore  |
| 0202-205078 | **SSPA-1-P121-O1-NE-LS-RL-JJM-WK2                | 0202-205212     | Will need to change the overlay(9916-100131) / no more display disabling(jumper 3) / no more tranquill mode / Different way of programming filtration cycle / Fonctionnalités different / No plugs on the pack anymore  |
| 0202-205079 | **SSPA-MP-P122-P212-O1-CP1-NE-LS-H4.0-JJM-D13    | Not replaceable | See D1 for replacement  |
| 0202-205080 | **SSPA-1-P122-B2-O1-CP2-LS-H4.0-JJM-RL-SR1       | 0202-205162     | Pump 1 always dual speed pump / Will need to change the overlay for a 9916-100240 / Fonctionnalités different / Jumper setting different  |
| 0202-205081 | **SSPA-1-P122-O2-LS-H4.0-JJM-HI                  | 0202-205212     | No clean-up or standby mode / Fonctionnalité different / No plugs on the pack anymore   |
| 0202-205082 | **SSPA-MP-P122-P212-B2-O2-LS-H4.0-JJM-HI         | 0202-205162     | No more standbye mode / Fonctionnalités different / Jumper setting different  |
| 0202-205083 | **SSPA-1-P122-P212-B2-O1-LS-JJM-AX8              | 0202-205162     | Jumper setting different / Pump 2 only single speed / Lock mode added / Fonctionnalités different   |
| 0202-205084 | **SSPA-1-P122-B2-O1-CP2-LS-JJM-MB1               | 0202-205162     | Will need to change the keypad for a TSC-9: 0202-007040 if system with one pump / Jumper setting different / Fonctionnalités different.   |
| 0202-205086 | **SSPA-1-P122-B2-O1-NE-LS-H5.5-JJM-DY1           | 3-72-7079       |   |
| 0202-205087 | **SSPA-MP-P122-P212-B2-O1-NE-LS-FB1-H5.5-JJM-DY1 | 0202-205162     | Fonctionnalités different / Jumper setting different  |

|             |  |                 |  |
|-------------|--|-----------------|--|
| 0202-205088 | **SSPA-MP-P122-P212-O1-CP1-NE-LS-HR-FB1-JJM-LA4      | 0202-205209     | No more ozone icon on keypad. Overlay will have to be changed if two pumps: 9916-100219, if two pumps and a blower: 9916-100219 / Jumper setting different / Fonctionnalités different   |
| 0202-205089 | **SSPA-MP-P122-P212-B2-O1-NE-LS-JJM-AX1              | 0202-205162     | If using a TSC-19, no more ozone icon. Will have to change the overlay for a 9916-100219 / Jumper setting different / Fonctionnalités different  |
| 0202-205092 | **SSPA-1-P121-P211-O1-NE-LS-H4.0-WK2                 | 3-72-7079       | If using a special shaped keypad, change the keypad for a 0202-007049. If a TSC-18 single pump system, change the overlay for a 9916-100239. If a TSC-18 dual pump system, change the overlay for a 9916-100240 / Fonctionnalités different  |
| 0202-205093 | **SSPA-MP-P122-P212-B2-O1-NE-LS-H5.5-JJM-RL-AX2      | 0202-205162     | Pump 2 always enabled / No more ozone icon, if using a single pump system change overlay for a: TSC-18: 9916-100240, TSC-19: 9916-100219. If dual pump system: TSC-18: 9916-100240, TSC-19: 9916-100219. If two pumps and blower: TSC-19: 9916-100219 / Jumper setting different / Fonctionnalités different   |
| 0202-205094 | **SSPA-MP-P122-P212-B1-O1-NE-LS-FB1-H4.0-JJM-SA1     | 0202-205162     | Pump 2 always enabled so if using a single pump system, will need to change the overlay for a 9916-100240 / Fonctionnalités different / Jumper setting different   |
| 0202-205096 | **SSPA-MP-P122-P212-B1-O1-CP1-NE-LS-HR-FB1-JJM-LA5   | 3-72-7107       |  |
| 0202-205097 | SSPA-1-P122-B2-O2-LS-FB1-H4.0-JJM-HI                 | 3-72-7079       | No clean-up or standby mode / Fonctionnalités different  |
| 0202-205098 | **SSPA-1-P122-B2-O1-CP2-NE-LS-H4.0-JJM-RL-SR2        | 0202-205162     | Will need to change the overlay TSC-18 9916-100240 / Pump 1 always dual speed / Blower not controlled by the Jet key but will have its own key / Low-level programming replaced by jumpers / Fonctionnalités different   |
| 0202-205099 | SSPA-1-P122-O1-NE-LS-H4.0-JJC                        | 0202-205212     | No plugs on the pack anymore   |
| 0202-205100 | SSPA-1-P122-O2-NE-LS-H4.0-JJC-T2                     | 0202-205212     | Replace transformer by a 560AA0430 / No plugs on the pack anymore  |
| 0202-205102 | **SSPA-MP-P122-P212-A11-A21-O2-NE-LS-H4.0-JJM-DY1    | 0202-205160     | No more internal fiber optic, if spa equipped with fiber optic will need to add an EXM-5 (0101-200013) + cable adaptor(9920-400398) / Fonctionnalités different / Jumper setting different   |
| 0202-205104 | **SSPA-MP-P122-P222-O1-NE-LS-AMP-ND3                 | 3-72-7078       | Pump 2 will become a single speed pump. If a 2 pump system, change the keypad for a 0202-007100  |
| 0202-205105 | **SSPA-1-P122-P212-O1-LS-H5.5-JJM                    | 3-72-7079       |  |
| 0202-205106 | **SSPA-1-P122-P211-O1-NE-LS-WK2                      | 3-72-7079       | If using a special shaped keypad, change the keypad for a 0202-007049. If a TSC-18 single pump system, change the overlay for a 9916-100239. If a TSC-18 dual pump system, change the overlay for a 9916-100240 / Fonctionnalités different  |
| 0202-205107 | **SSPA-MP-P122-P212-O1-CP1-NE-LS-FB1-HR-JJM-MA2      | 0202-205209     | Pump 2 always enabled, if using a single pump system will need to change the overlay: TSC-18: 9916-100240 / Fonctionnalités different / Jumper setting different   |
| 0202-205108 | **SSPA-1-P122-O1-NE-LS-H5.5-JJC-HY1                  | 0202-205212     | No plugs on the pack anymore   |
| 0202-205109 | **SSPA-MP-P122-P212-B1-O1-NE-LS-H5.5-JJC-HY2         | 0202-205160     | Standby mode added / Fonctionnalités different / Jumper setting different  |
| 0202-205110 | **SSPA-MP-P122-P212-B1-O1-CP1-NE-LS-HR-FB1-JJC-LA5   | 3-72-7107       |  |
| 0202-205111 | **SSPA-MP-P122-P212-B1-O1-NE-LS-FB1-JJM-SA1          | 0202-205162     | Pump 2 always enabled, if single pump system, will have to change the overlay for a 9916-100240 / Fonctionnalités different / Jumper setting different   |
| 0202-205112 | **SSPA-1-P122-O1-NE-LS-JJM-MA2                       | 0202-205212     | No plugs on the pack anymore   |
| 0202-205113 | **SSPA-MP-P122-P212-B2-O2-NE-LS-FB1-H4.0-JJM-DY2     | 0202-205160     | Fonctionnalités different / Jumper setting different   |
| 0202-205114 | **SSPA-MP-P122-P212-B1-O1-NE-LS-H5.5-AMP-HS2         | 0202-205163     | Auxiliary switch not compatible anymore / Standby mode added / Fonctionnalités different   |
| 0202-205116 | **SSPA-MP-P122-P212-P312-B1-O1-CP1-NE-LS-FB1-JJC-LA6 | 3-72-7107       |  |
| 0202-205117 | **SSPA-MP-P122-P212-O2-CP2-NE-LS-FB2-T2-HR-JJM-MA3   | 0202-205209     | Transformer 120VAC so will need to change the transformer for a 530AA0430 / Pump 2 always enabled so if using a single speed pump system, will need to change the overlay for a 9916-100240 / Pump 1 always dual speed / Fonctionnalités different / Jumper setting different  |
| 0202-205118 | **SSPA-1-P122-P212-O1-NE-LS-H4.0-JJM-DY1             | 3-72-7079       |  |
| 0202-205119 | **SSPA-1-P122-O1-NE-LS-H4.0-JJM-DY2                  | 0202-205212     | No plugs on the pack anymore   |
| 0202-205126 | **SSPA-1-P122-P212-O2-NE-LS-T2-H1.0-WK2              | 3-72-7079       | If using a special shaped keypad, change the keypad for a 0202-007049. If a TSC-18 single pump system, change the overlay for a 9916-100239. If a TSC-18 dual pump system, change the overlay for a 9916-100240 / Fonctionnalités different / Transformer is now a 120VAC so change the transformer for a 530AA0430  |
| 0202-205127 | **SSPA-1-P122-P212-O1-NE-LS-H4.0-JJM-RL-CC3          | 3-72-7079       |  |
| 0202-205129 | SSPA-1-P121-O1-NE-LS-H4.0-JJC-MB2                    | 0202-205212     | No plugs on the pack anymore   |
| 0202-205130 | *SSPA-1-P122-P212-O1-NE-LS-H4.0-JJC-RL-CC4           | 3-72-7079       |  |
| 0202-205131 | *SSPA-MP-P112-P212-B2-A12-LS-HR-T2-AMP-LC1           | Not replaceable | See Lasco for replacement  |
| 0202-205132 | *SSPA-MP-P122-B2-O1-CP2-NE-LS-H4.0-JJC-RL-SR3        | 0202-205162     | Will need to change the overlay TSC-18 9916-100240 / Blower not controlled by the Jet key but will have its own key / Low-level programming replaced by jumpers / Pump 1 always dual speed pump / When in smart winter mode, display will show the filtration cycle icon flashing and no "AFP" anymore / Display will not show "Ftr" or "Pur" during purge or filtration cycle / Fonctionnalités different |

|             |  |                 |   |
|-------------|--|-----------------|---|
| 0202-205134 | *SSPA-MP-P122-P212-B2-O1-NE-LS-JJC-RL-AX3                  | 0202-205162     | Pump 2 always enabled / No more ozone icon, if using a single pump system change overlay for a: TSC-18: 9916-100240, TSC-19: 9916-100219. If dual pump system: TSC-18: 9916-100240, TSC-19: 9916-100219. If two pumps and blower: TSC-19: 9916-100219 / Jumper setting different / Functionalities different  |
| 0202-205135 | *SSPA-MP-P122-P212-B2-O1-NE-LS-H.5-AU1-JJC-RL-AX3          | 0202-205162     | Pump 2 always enabled / No more ozone icon, if using a single pump system change overlay for a: TSC-18: 9916-100240, TSC-19: 9916-100219. If dual pump system: TSC-18: 9916-100240, TSC-19: 9916-100219. If two pumps and blower: TSC-19: 9916-100219 / Jumper setting different / Functionalities different  |
| 0202-205137 | *SSPA-MP-P122-P222-O1-CP1-NE-LS-FB1-HR-JJM-PA1             | 0202-205209     | Pump 2 only single speed / Functionalities different / Jumper setting different   |
| 0202-205138 | SSPA-MP-P122-P222-O1-CP1-NE-LS-FB1-H5.5-JJM-PA2            | 0202-205162     | Pump 2 can only be 1 speed / Jumper setting different / Functionalities different   |
| 0202-205140 | SSPA-MP-P122-P212-B1-O1-LS-H5.5-JJC-BF1                    | 0202-205162     | Change keypad for a 0202-007089 / Functionalities different   |
| 0202-205143 | *SSPA-1-P122-P212-O1-NE-H4.0-RL-FB1-JJC-CC5                | 3-72-7079       | IR sensor not compatible anymore  |
| 0202-205144 | SSPA-1-P122-B2-O1-CP2-LS-JJC-MB3                           | 0202-205162     | Pump1 can only be configured with 2 speeds / Will need to change the keypad for a TSC-9: 0202-007040 if system with one pump / Jumper setting different / Functionalities different   |
| 0202-205145 | SSPA-MP-P122-P212-B1-O1-LS-H4.0-JJC-BF2                    | 0202-205162     | If single or dual pump system, will need to change the overlay for a 9916-100219. If 2 pumps and a blower, will need to change the keypad for a 0202-007088 / Functionalities different / Jumper setting different  |
| 0202-205146 | SSPA-MP-P122-P212-B2-O1-NE-LS-H.5.5-AU1-JJC-RL-AX4         | 0202-205162     | Pump 2 always enabled / No more ozone icon, if using a single pump system change overlay for a: TSC-18: 9916-100240, TSC-19: 9916-100219. If dual pump system: TSC-18: 9916-100240, TSC-19: 9916-100219. If two pumps and blower: TSC-19: 9916-100219 / Jumper setting different / Functionalities different  |
| 0202-205148 | */SSPA-MP-P122-B2-O1-CP2-NE-LS-H4.0-JJC-RL-AU1-SR4         | 0202-205162     | Will need to change the overlay TSC-18 9916-100240 / Pump 1 can only be set as a 2 speed pump / Pump 2 always enabled / Blower not controlled by the Jet 1 key but will have its own key / Low-level programming replaced by jumpers / When in smart winter mode, display will show the filtration cycle icon flashing and no "AFP" anymore / Display will not show "Ftr" or "Pur" during purge or filtration cycle / Functionalities different |
| 0202-205149 | *SSPA-MP-P122-P212-B2-O1-NE-LS-AU1-JJC-RL-AX4              | 0202-205162     | Pump 2 always enabled / No more ozone icon, if using a single pump system change overlay for a: TSC-18: 9916-100240, TSC-19: 9916-100219. If dual pump system: TSC-18: 9916-100240, TSC-19: 9916-100219. If two pumps and blower: TSC-19: 9916-100219 / Jumper setting different / Functionalities different  |
| 0202-205154 | SC-MP-P122-P212-B1-O1-LS-HP- U-JJC-BF3                     | Not replaceable | See Blue Falls for replacement  |
| 0202-205155 | SC-MP-P121-P211-B1-O1-LS-H5.5 JJC-NP1                      | 0202-205162     | If single or dual pump system, will need to change the overlay for a 9916-100219. If 2 pumps and a blower, will need to change the keypad for a 0202-007088 / Functionalities different / Jumper setting different  |
| 0202-205156 | SC-CF-P122-P212-O1-AU11-H4.0- U-RL-JJC-NE-CC7              | 3-72-7079       | IR sensor not compatible anymore  |
| 0202-205157 | *SC-MP-P122-P212-B2-O1-AU11- LS-H4.0-U-RL-JJC-NE-SR5       | 0202-205162     | Pump 2 always enabled / If using a single pump system, change the overlay for a 9916-100240 / If using 2 pumps and a blower, change the overlay for a 9916-100219 / Low-level programming replaced by jumpers / Functionalities different   |
| 0202-205158 | SC-CF-P122-02-AU12-LS-H4.0-U -AMP-HI1                      | 3-72-7078       | No clean-up or standby mode / Functionalities different   |
| 0202-205160 | SC-MP-P122-P212-B1-O1-CP1-AU11-LS-H4.0-U-L-CD-JJC-NE-SBD   | 0202-205160     |   |
| 0202-205161 | SC-MP-P122-P212-B1-O1-CP1-AU11-LS-H4.0-U-AMP-NE-SBD        | 0202-205162     | Comes with JJM plugs instead of AMP plugs   |
| 0202-205162 | SC-MP-P122-P212-B1-O1-CP1-AU11-LS-H4.0-T2-U-JJC-NE-SBD     | 0202-205162     |   |
| 0202-205163 | SC-MP-P122-P212-B1-O1-CP1-AU11-LS-H4.0-T2-U-LCD-AMP-NE-SBD | 0202-205163     |   |
| 0202-205201 | *SC-1-P122-P212-O1-NE-H4.0-RL- AU1-JJC-CC6                 | 3-72-7079       |   |
| 0202-205203 | SC-MP-P122-P212-B2-O1-AU11-LS -U-RL-JJC-NE-AX5             | 0202-205162     |   |
| 0202-205204 | SC-MP-P122-P212-B2-O1-AU11-LS H5.5-U-RL-JJC-NE-AX5         | 0202-205162     |   |
| 0202-205205 | *SC-MP-P122-P222-O1-CP1-LS- H5.5-U-FBI-JJM-AD1             | 0202-205162     | Pump 2 can only be 1 speed / No suspend mode / Filter cycle setting different / Jumper setting different / Functionalities different  |
| 0202-205206 | SC-MP-P122-P212-B2-02-CP2- AU12-LS-H4.0-U-EE-RL-JJC-SR6    | 0202-205162     | Pump 1 can only be a dual speed pump / Pump 2 always enabled, if using a one pump system, change the overlay for a 9916-100219 / If using a system with 2 pumps and a blower, change the overlay for a 9916-100219 / Low-level programming replaced by jumpers / Functionalities different  |
| 0202-205207 | *SC-MP-P122-P212-B2-01-AU11- LS-H5.5-U-IF-RL-JJC-NE-AX5    | 0202-205162     | Pump 2 always enabled / No more ozone icon, if using a single pump system change overlay for a: TSC-18: 9916-100240, TSC-19: 9916-100219. If dual pump system: TSC-18: 9916-100240, TSC-19: 9916-100219. If two pumps and blower: TSC-19: 9916-100219 / Jumper setting different / Functionalities different  |
| 0202-205209 | SC-MP-P122-P212-B1-O1-CP1AU11-LS-HR-U-JJC-NE-SBD           | 0202-205209     |   |
| 0202-205210 | SC-CF-P122-LS-H4.0-U-NE-D11                                | Not replaceable | See D1 for replacement  |
| 0202-205211 | SC-CF-P12-P21-O-LS-H5.5-U-RL-WK1                           | 3-72-7079       | If a 2 pumps system will need to change the overlay for a 9916-100240 / Different functionalities   |
| 0202-205212 | SC-CF-P12-O-CP-LS-H4.0-U-GE1                               | 0202-205212     |   |
| 0202-205213 | SC-MP-P122-P212-O1-LS-HP-U-JJC-AP4                         | 0202-205209     | Pump 2 always enabled, so if using a single pump will need to change the overlay: TSC-9: 9916-100186 ; TSC-18: 9916-100240 ; TSC-19: 9916-100219 / Functionalities different / Jumper setting different   |

|             |  |                 |   |
|-------------|--|-----------------|---|
| 0202-205214 | SC-MP-P122-P212-B1-01-CP1-AU11-LS-H5.5-T2-U-JJC-NE-SBD | 0202-205162     | Will need to change the transformer for a 530AA0430   |
| 0202-205215 | SC-CF-P121-P211-01-LS-H5.5-U-JJC-NE-SBD                | 3-72-7079       |   |
| 0202-205216 | SC-CF-P12-P21-O-AU1-LS-H4.0-U-NE-SBD                   | 3-72-7079       | JJ plugs supplied with new pack   |
| 0202-205217 | SC-MP-P112-O2-CP2-LS-HP-U-AMP-MA1                      | Not replaceable | See Artesian for replacement  |
| 0202-207001 | **SSPA-1-P122-O1-LS-JJM-PP                             | 0202-205212     | No plugs on the pack anymore  |
| 0202-207002 | *SSPA-1-P122-B2-O1-CP2-LS-JJC-AX6-PP                   | 0202-205162     | Pump 2 always enabled, overlay will have to be changed if single pump system: TSC-9, 9916-100186; TSC-18, 9916-100240; TSC-19, 9916-100219 / Jumper setting different / Fonctionnalités different   |
| 0202-207003 | **SSPA-1-P122-O1-CP2-LS-JJM-AX7-PP                     | 0202-205212     | Jumper setting different / Fonctionnalités different / No plugs on the pack anymore   |
| 0202-207004 | SSPA-1-P121-P211-O1-NE-LS-H4.0-AMP-PPD                 | 3-72-7078       |   |
| 0202-207005 | SSPA-1-P121-P211-O1-NE-LS-H4.0-JJC-PPD                 | 3-72-7079       |   |
| 0202-207006 | **SSPA-1-P121-LS-H1.38-JJM-RL-PP                       | 0202-205212     | No plugs on the pack anymore  |
| 0202-207007 | **SSPA-1-P122-LS-H5.5-JJM-PP                           | 0202-205212     | No plugs on the pack anymore  |
| 0202-207008 | SSPA-1-P121-P211-O1-NE-LS-AMP-PPD                      | 3-72-7078       |   |
| 0202-207009 | SSPA-1-P121-P211-O1-NE-LS-JJC-PPD                      | 3-72-7079       |   |
| 3-62-7001   | B-SC-CF-P12-P21-O-NE-L-NW-PD1                          | Not replaceable | See PDC for replacement   |
| 3-62-7010   | B-SC-MP-P12-P22-O-NE-L-EE-NW- HQ3/33-0024D-R2          | Not replaceable | See HQ for replacement  |
| 3-62-7011   | *B-SC-MP-P12-P21-O-NE-L-EE-T2- -NW-HQ4/33-0024A-R4     | Not replaceable | See HQ for replacement  |
| 3-62-7012   | B-SC-CF-P12-P21-O-CP-L-EE-NW- HQ/33-0024-R6            | Not replaceable | See HQ for replacement  |
| 3-62-7013   | *B-SC-CF-P12-P21-O-CP-L-EE-T2- NW-HQ/33-0024A-R3       | Not replaceable | See HQ for replacement  |
| 3-62-7014   | B-SC-MP-P12-P21-B-O-CP-NE-L- ee-NW-HQ5/33-0024B-R4     | Not replaceable | See HQ for replacement  |
| 3-62-7015   | *B-SC-MP-P12-P21-B-O-CP-NE-L-EE-T2-NW-HQ5/33-0024C-R3  | Not replaceable | See HQ for replacement  |
| 3-62-7017   | B-SC-MP-P12-P2-O-L-IR-U-CC5                            | 3-72-7079       | IR sensor not compatible anymore  |
| 3-62-7019   | B-SC-MP-P12-P21-B-O-CP-NE-L- EE-NW-U-HQ6 (NOTE)        | Not replaceable | See HQ for replacement  |
| 3-72-7006   | *SC-CF-P121-NE-LS-H1.0-WK                              | 0202-205212     | Will need to change the overlay(9916-100131) / no more display disabling(jumper 3) / no more tranquill mode / Different way of programming filtration cycle / Fonctionnalités different   |
| 3-72-7007   | *SC-CF-P121-O1-NE-LS-H1.0 RL-JJM-WK2                   | 0202-205212     | Will need to change the overlay(9916-100131) / no more display disabling(jumper 3) / no more tranquill mode / Different way of programming filtration cycle / Fonctionnalités different / No plugs on the pack anymore  |
| 3-72-7009   | SC-CF-P121-O1-LS-U-RL-JJM-NE- WK2                      | 0202-205212     | Will need to change the overlay(9916-100131) / no more display disabling(jumper 3) / no more tranquill mode / Different way of programming filtration cycle / Fonctionnalités different / No plugs on the pack anymore  |
| 3-72-7011   | *SC-CF-P121-P211-O1-NE-LS H4.0-WK2                     | 3-72-7079       | If using a special shaped keypad, change the keypad for a 0202-007049. If a TSC-18 single pump system, change the overlay for a 9916-100239. If a TSC-18 dual pump system, change the overlay for a 9916-100240 / Functionalities different   |
| 3-72-7013   | SC-CF-P122-B1-01-LS-H5.5-U- JJM-NE-SU1                 | 3-72-7079       |   |
| 3-72-7014   | SC-CF-P122-B1-01-LS-U-JJC NE-MG1                       | 3-72-7079       | No more standby mode / Fonctionnalités different  |
| 3-72-7016   | SC-CF-P122-B2-O2-CP1-LS-HP-U -AMP-NE-AP2               | 0202-205209     | Comes with JJM plugs only, so will need to re-use the Amp plugs from the old pack / Pump 2 always enabled, so if using a single pump will need to change the overlay: TSC-9: 9916-100186 ; TSC-18: 9916-100240 ; TSC-19: 9916-100219 / Fonctionnalités different / Jumper setting different |
| 3-72-7021   | SC-CF-P122-O1-LS-U-JJM-NE-MA2                          | 0202-205212     | No plugs on the pack anymore  |
| 3-72-7023   | SC-CF-P121-P211-O1-LS-U-NE- WK2                        | 3-72-7079       | If using a special shaped keypad, change the keypad for a 0202-007049. If a TSC-18 single pump system, change the overlay for a 9916-100239. If a TSC-18 dual pump system, change the overlay for a 9916-100240 / Functionalities different   |
| 3-72-7025   | SC-MP-P122-O1-LS-U-AMP-NE-ND2                          | 0202-205212     | No plugs on the pack anymore  |
| 3-72-7031   | SC-MP-P122-P212-B1-01-AU11- LS-U-JJM-NE-SA1            | 0202-206162     | Pump 2 always enabled so if using a single pump system, will need to change the overlay for a 9916-100240 / Fonctionnalités different / Jumper setting different  |
| 3-72-7032   | SC-MP-P122-P212-O1-CP1-L2S-U- LCD-AMP-NE-HY3           | 0202-205209     | Comes with JJM plugs only, so will need to re-use the Amp plugs from the old pack / Will need to change the keypad, if single pump system: 0202-007103, if dual pump system: 0202-007104 / Auxiliary switches not supported anymore / Fonctionnalités different / Jumper setting different  |
| 3-72-7034   | SC-MP-P122-P212-O1-CP1-LS- H4.0-U-JJM-NE-D13           | Not replaceable | See D1 for replacement  |
| 3-72-7035   | SC-MP-P122-P222-O1-LS-U- AMP-ND3                       | 3-72-7078       | Auxiliary switch not compatible anymore / Pump 2 will become a single speed pump / Jumper setting different   |
| 3-72-7036   | SC-MP-P122-P212-B1-01-LS-H5.5 -U-LCD-AMP-NE-HS2        | 0202-205163     | Auxiliary switch not compatible anymore / Standby mode added / Fonctionnalités different  |
| 3-72-7048   | SC-CF-P122-O1-LS-H4.0-U-JJC- NE-DY2                    | 0202-205212     | No plugs on the pack anymore  |
| 3-72-7053   | SC-MP-P122-P212-P311-O1-CP1- AU11-LS-U-JJC-NE-LA7      | 3-72-7107       |   |

|           |  |                 |  |
|-----------|--|-----------------|--|
| 3-72-7062 | SC-MP-P121-O1-CP1-NE-LS-H4.0-AU1-JJM-SA2                         | 0202-205162     | Will need to change the overay, if a TSC-18 change for a 9916-100240, if a TSC-35 change for a 9916-100381 / No more economy mode / Fonctionnalités different / Jumper setting different                         |
| 3-72-7063 | SC-MP-P122-P212-O1-CP1-NE-LS AMP-ND5                             | 0202-205161     | Pump 2 always enabled, if using a single pump system, change overlay for a 9916-100240 / Jumper setting different / Fonctionnalités different  |
| 3-72-7068 | SC-CF-P122-B2-O1-AU11-LS-H4.0 -U-AMP-EM1                         | 3-72-7078       |  |
| 3-72-7069 | SC-MP-P122-B2-O2-CP2-LS-H5.5 -JJC-NE-RW1                         | 0202-205162     | Pump 2 is always enabled so will need to change the overlay for a 9916-100186 if system with one pump / Jumper setting different / Fonctionnalités different   |
| 3-72-7070 | SC-CF-P122-O2-LS-H5.5-U-JJC- NE-RW2                              | 0202-205212     | No plugs on the pack anymore   |
| 3-72-7078 | SC-CF-P121-P211-O1-LS-H4.0-U- AMP-NE-SBD                         | 3-72-7078       |  |
| 3-72-7079 | SC-CF-P121-P211-O1-LS-H4.0-U- JJC-NE-SBD                         | 3-72-7079       |  |
| 3-72-7080 | SC-CF-P122-P212-O1-LS-H4.0-U -JJC-NE-DY3                         | 3-72-7079       |  |
| 3-72-7082 | SC-MP-P122-P212-B2-O1-AU11-LS -H4.0-U-FB1-JJC-NE-DY5             | 0202-205160     | Functionnalities different / Jumper setting different  |
| 3-72-7083 | SC-CF-P122-B2-O1-AU11-LS-U- AMP-EM2                              | 3-72-7078       |  |
| 3-72-7086 | SC-CF-P122-B1-O1-LS-U-JJM-NE SU1                                 | 3-72-7079       |  |
| 3-72-7093 | SC-MP-P122-P212-O1-CP2-NE-LS-FB1-HR-JJM-MA7                      | 0202-205209     | Pump 2 always enabled, if using a single pump system will need to change the overlay: TSC-18: 9916-100240 / Fonctionnalités different / Jumper setting different   |
| 3-72-7100 | SC-CF-P122-O1-LS-U-JJM-NE-SA2 (THIS IS REPLACING 3-72-7044)      | 0202-205212     | No plugs on the pack anymore   |
| 3-72-7103 | SC-MP-P122-P212-B2-O1-AU11-LS U-JJC-NE-DY5                       | 0202-205160     | Functionnalities different / Jumper setting different  |
| 3-72-7104 | SC-MP-P122-P212-AU11-AU21-01- LS-U-JJC-NE-DY1                    | 0202-205160     | No internal fiber optic, will need to add an EXM-5(0101-200013) + cable adaptor(9920-400398) / Jumper setting different / Fonctionnalités different  |
| 3-72-7105 | SC-MP-P122-P212-B2-O1-AU11-LS U-JJC-NE-DY3                       | 0202-205160     | Functionnalities different / Jumper setting different  |
| 3-72-7106 | SC-MP-P122-P212-O1-AU11-AU21- LS-H4.0-U-JJC-NE-DY4               | 0202-205160     | No internal fiber optic, will need to add an EXM-5(0101-200013) + cable adaptor(9920-400398) / Jumper setting different / Fonctionnalités different  |
| 3-72-7107 | SC-MP-P122-P212-P311-O1-CP1- AU11-LS-U-JJC-NE                    | 3-72-7107       |  |
| 3-72-7108 | SC-MP-P121-P211-O1-CP1-NE-LS H4.0-JJC-SBD1                       | 0202-205162     |  |
| 3-72-7125 | SC-CF-P122-P212-O1-LS-H4.0-U -JJC-NE-TR1                         | 3-72-7079       |  |
| 3-72-7126 | SC-CF-P122-P212-O1-NE-LS-H5.5-JJC-HY4                            | 3-72-7079       |  |
| 3-72-7127 | SC-MP-P122-P212-B2-O1-CP2- AU11-LS-HR-U-JJC-MA10                 | 0202-205209     | Pump 2 always enabled, if using a single pump system will need to change the overlay: TSC-18: 9916-100240, TSC-19: 9916-100219 / Pump 1 always dual speed / Fonctionnalités different / Jumper setting different |
| 3-72-7128 | SC-MP-P122-P212-B2-O1-CP2- AU11-LS-HR-U-LCD-JJC-MA9              | Not replaceable | See Artesian for replacement   |
| 3-72-7129 | SC-MP-P122-P212-B1-O1-CP1- AU11-LS-HR-U-IR-LCD-JJC-NE-LA8        | Not replaceable | See LA for replacement   |
| 3-72-7131 | SC-CF-P122-P212-O1-AU11-LS- H4.0-U-JJC-NE-SA3                    | 3-72-7079       |  |
| 3-72-7133 | SC-MP-P122-P212-312-O1-CP1- AU11-LS-H4.0-U-RL-LCD-TSC-JJC-NE-SA5 | Not replaceable | See Saratoga for replacement   |
| 3-72-7135 | SC-CF-P121-P211-O1-LS-U-AMP- NE-SBD                              | 3-72-7078       |  |
| 3-72-7136 | SC-CF-P121-P211-O1-LS-U-JJC- NE-SBD                              | 3-72-7079       |  |
| 3-72-7137 | SC-MP-P121-P211-O1-CP1-LS-U- JJC-NE-SBD1                         | 0202-205162     |  |
| 3-72-7139 | SC-MP-P122-P212-P312-O1-CP1- AU11-LS-U-RL-LCD-TSC-JJC-NE-SA6     | Not replaceable | See Saratoga for replacement   |
| 3-72-7140 | SC-CF-P122-P212-O1-AU11-LS-U- JJC-NE-SA4                         | 3-72-7079       |  |
| 3-72-7141 | SC-CF-P122-P212-O1-LS-H4.0-U -JJC-NE-HY5                         | 3-72-7079       |  |
| 3-72-7142 | SC-MP-P122-P212-B2-O1-LS-H4.0 U-LCD-JJC-NE-HY3                   | 0202-205160     | No more kinetic lighting option / Auxiliary switch not compatible anymore / Fonctionnalités different / Jumper setting different   |
| 3-72-7143 | *SC-CF-P121-P211-O1-LS-H4.0- U-IF-AMP-NE-SBD                     | 3-72-7078       |  |
| 3-72-7144 | *SC-CF-P121-P211-O1-LS-H4.0- U-IF-JJC-NE-SBD                     | 3-72-7079       |  |
| 3-72-7146 | *SC-MP-P122-P222-O2-CP2-LS-HR -U-LCD-EE-JJC-NE-DY6               | Not replaceable | See Dynasty for replacement  |
| 3-72-7147 | **SC-CF-P122-P212-O1-AU12-LS-H4.0-U-JJC-NE-PD1                   | 3-72-7079       |  |
| 3-72-7159 | SC-MP-P122-P212-B1-O1-CP1-AU11-LS-HR-U-IR-LCD-JJC-NE-LA8         | Not replaceable | See LA for replacement   |