

ID	Description	Replacement product	Modification or comments
0201-100001	**MAS-MSPA-5-P12-P22-B-O-L-HQ	not replaceable	See HQ for replacement
0201-100002	**MAS-MSPA-4-P12-P21-B-O-NE-L-MG	0201-300045	Will need to replace the transformer and probes. Replace overlay for 9916-100094
0201-100003	**MAS-MSPA-4-P12-P22-B-O-L-CP-T2-HQ	not replaceable	See HQ for replacement
0201-100004	**MAS-MSPA-2-P122-P212-L-T2-HQ1	not replaceable	See HQ for replacement
0201-100005	**MAS-MSPA-1-P12-P22-B-O-L-HQ	not replaceable	See HQ for replacement
0201-100006	//MAS-MSPA-1-P12-P22-B-O-L-CP-D1	not replaceable	See D1 for replacement
0201-100008	**MAS-MSPA-4-P12-P22-B-O-L-CP-HQ	not replaceable	See HQ for replacement
0201-100010	**MAS-MSPA-5-P12-P22-O-B-L-T2-HQ	not replaceable	See HQ for replacement
0201-100011	**MAS-MSPA-2-P12-P22-O-L-D1	3-72-7079	Need to replace the overlay: 1 pump system 9916-100131 / 2 pump system 9916-100186 / Auxiliary keypad not compatible with new system / Fonctionnalités different.
0201-100013	**MAS-MSPA-MP-P12-P22-O-CP-NE-A1-L-RTC-NW-D11	not replaceable	See D1 for replacement
0201-100014	MAS-MSPA-5-P12-P22-B-O-NE-L-NW-HQ	not replaceable	See HQ for replacement
0201-100015	*MAS-MSPA-4-P12-P22-B-O-CP-NE-L-T2-NW-HQ	not replaceable	See HQ for replacement
0201-100016	MAS-MSPA-4-P12-P22-B-O-CP-NE-L-NW-HQ	not replaceable	See HQ for replacement
0201-100017	MAS-MSPA-5-P12-P22-B-O-NE-L-T2-NW-HQ	not replaceable	See HQ for replacement
0201-100018	**MAS-MSPA-MP-P12-P21-BV-O-NE-A1-LS-RTC-IR-L-FB-MG	0201-300014	Need to change the overlay for 9916-100094 / Blower not variable anymore / No quiet key anymore / Fonctionnalités different.
0201-100020	**MAS-MSPA-MP-P12-P22-O-CP-NE-A1-L-RTC-SPW-NW-D11	not replaceable	See D1 for replacement
0201-100022	**MAS-MSPA-MP-P12-P22-P31-B-O-CP-NE-A1-LS-IR-SPW-PD1	0201-300014	Need to change the overlay for a 9916-100723 / No more safety light/radio switch / Fonctionnalités different.
0201-100023	**MAS-MSPA-MP-P12-P22-P31-B-O-CP-NE-LS-2LS-RTC-IR-HQ1	not replaceable	See HQ for replacement
0201-100025	**MAS-MSPA-MP-P12-P21-P31-B-O-CP-NE-A1-A2-RTC-SPW-NW-D14	not replaceable	See D1 for replacement
0201-100029	**MAS-MSPA-MP-P12-P22-P31-B-O-CP-NE-A1-A2-L-RTC-SPW-IR-HQ2	not replaceable	See HQ for replacement
0201-100033	**B-MC-MP-P12-P22-O-CP-NE-A1-A2-L-RTC-SPW-NW-D15	not replaceable	See D1 for replacement
0201-100035	**MAS-MSPA-MP-P12-P22-P31-B-O-CP-NE-A1-LS-IR-SPW-PD2	0201-300014	Need to change the overlay for a 9916-100723 / No more safety light/radio switch / Fonctionnalités different.
0201-100036	B-MC-MP-P12-P22-O-CP-A1-L-RTC-SPW-NW-D17	not replaceable	See D1 for replacement
0201-100037	B-MC-MP-P12-P22-O-CP-A1-A2-L-RTC-SPW-NW-D18	not replaceable	See D1 for replacement
0201-201001	**MSPA-1-P122-P222-B1-O1-L2S-JJM-BF	0201-300045	Will need to replace the transformer and probes.
0201-201003	**MSPA-1-P122-P222-B2-O2-NE-LS-H5.5-AMP-T2-RL-SB	0201-300045	Will need to replace the transformer and probes / Transformer 120VAC so will need to have a neutral wire.
0201-201004	**MSPA-1-P122-P212-B2-O2-NE-LS-HP-AMP-T2-AP	0201-300045	Will need to replace the transformer and probes / Transformer 120VAC so will need to have a neutral wire.
0201-201005	**MSPA-1-P122-P212-B2-O1-CP2-L2S-HVS-JJM-AX3	0201-300045	Will need to replace the transformer and probes.
0201-201008	MSPA-3-P131-P231-LA-AMP	not replaceable	See Aquatic Industries for replacement
0201-201009	**MSPA-1-P122-P222-B2-O1-FB-NE-LS-H5.5-JJM-RL-AL	0201-300045	Will need to replace the transformer and probes.
0201-201010	**MSPA-1-P112-P212-B2-O1-CP2-LS-HV-JJM-NF-AX2	0201-300045	Will need to replace the transformer and probes.
0201-201011	**MSPA-1-P122-P222-B2-O2-CP2-NE-LS-FB-HV-AMP-T2-RL-SB	0201-300045	Will need to replace the transformer and probes / Transformer 120VAC so will need to have a neutral wire.
0201-201013	**MSPA-1-P122-P222-B1-O1-LS-H5.5-JJM-SO	0201-300045	Will need to replace the transformer and probes.

0201-201014	**MSPA-2-P122-O1-LS-H5.5-JJM	3-72-7079	Need to replace the overlay: 1 pump system 9916-100131 / 2 pump system 9916-100186 / Auxiliary keypad not compatible with new system / Functionalities different.
0201-201015	**MSPA-1-P122-P222-BH1-O1-CP2-FB-LS-JJM-LA3	0201-300045	No more blower heater / Will need to replace the transformer and probes.
0201-201016	**MSPA-1-P122-P222-B1-O1-LS-JJM-SW	0201-300045	Will need to replace the transformer and probes.
0201-201017	**MSPA-1-P122-P212-B1-O1-LS-H5.5-AMP	0201-300045	Will need to replace the transformer and probes.
0201-201018	**MSPA-1-P122-P222-B1-O1-L2S-JJM-BF2	0201-300045	Will need to replace the transformer and probes.
0201-201019	**MSPA-1-P122-P222-BH1-O1-CP2-LS-HB-JJM-LA2	0201-300045	If using a model 2500 keypad, change the overlay for a 9916-100130 / No more blower heater / Will need to replace the transformer and probes.
0201-201020	**MSPA-1-P122-P222-B2-O1-LS-H5.5-AMP-SF	0201-300045	Will need to replace the transformer and probes.
0201-201021	**MSPA-4-P122-P212-P312-B2-O1-CP1-L1-IR-HVS-JJM-MA1	0201-300045	Will need to replace the transformer and probes.
0201-201022	**MSPA-1-P112-P212-B1-O1-CP1-LS-HVS-AMP-SC	0201-300045	Will need to replace the transformer and probes.
0201-201023	**MSPA-4-P122-P212-P312-B2-O1-CP1-L1-HVS-JJM-MA1	0201-300045	Will need to replace the transformer and probes.
0201-201024	**MSPA-1-P122-P212-B1-O1-L2S-AMP-HY1	0201-300045	Will have to replace the overlay for a 9916-100130 / Optical ozonator light not available anymore / Optional switch(tsc-29) not compatible / Will need to replace the transformer and probe.
0201-201025	**MSPA-1-P122-P212-B1-O1-L2S-H5.5-AMP-HY1	0201-300045	Will have to replace the overlay for a 9916-100130 / Optical ozonator light not available anymore / Optional switch(tsc-29) not compatible / Will need to replace the transformer and probe.
0201-201026	**MSPA-1-P122-P222-B2-O1-LS-HB5.-5-NF-AMP-DK	0201-300045	Will need to replace the transformer and probes.
0201-201027	**MSPA-1-P122-B2-O1	0201-300045	Will need to replace the transformer and probes.
0201-201028	**MSPA-3-P122-P222-LS-AMP-T2	not replaceable	See Aquatic Industries for replacement
0201-201031	**MSPA-1-P122-P212-B2-O1-NE-LS-H5.5-AMP-SL	0201-300045	Will need to replace the transformer and probes.
0201-201032	**MSPA-1-P122-P222-B1-O1-L2S-HP-JJM-BF2	0201-300045	Will need to replace the transformer and probes.
0201-201033	**MSPA-1-P122-P222-B1-O1-FB-LS-H5.5-JJM	0201-300045	Will need to replace the transformer and probes.
0201-201035	**MSPA-1-P122-P222-B2-O2-CP2-NE-LS-HP-AMP-DK2	0201-300045	Will need to replace the transformer and probes.
0201-201036	**MSPA-1-P122-P222-B1-O1-CP1-L2S-HP-JJM-BF3	0201-300045	Will need to replace the transformer and probes.
0201-201037	**MSPA-1-P122-P212-B2-O1-CP2-LS-HVS-JJM-AX3	0201-300045	Will need to replace the transformer and probes.
0201-201039	**MSPA-4-P122-P212-B1-O1-NE-LS-FB-H35.5-AMP-OM	0201-300045	Will need to replace the transformer and probes.
0201-201040	**MSPA-1-P122-P222-B1-O1-CP1-L2S-JJM-BF3	0201-300045	Will need to replace the transformer and probes.
0201-201043	*/MSPA-1-P122-P222-BH1-O1-CP2-FB-LS-HB-JJC-LA4	0201-300045	If using a model 2500 keypad, change the overlay for a 9916-100130 / No more blower heater / Will need to replace the transformer and probes.
0201-201046	**MSPA-1-P122-P212-B2-O1-FB-A1-HB-LS-JJM-AX4	0201-300045	Will need to replace the transformer and probes.
0201-207001	*MSPA-1-P122-P222-B1-O1-CP1-NE-LS-FB-H5.5-T2-AMP-PPD	0201-300045	Will need to replace the transformer and probes / Transformer 120VAC so will need to have a neutral wire.
0201-207002	**MSPA-1-P122-P222-B1-O1-CP-NE-LS-FB-HVS4.0-T2-AMP-PPD	0201-300045	Will need to replace the transformer and probes / Transformer 120VAC so will need to have a neutral wire.
0201-207003	*MSPA-1-P122-P222-B1-O1-CP1-NE-LS-FB-H5.5-T2-JJC-PPD	0201-300045	Will need to replace the transformer and probes / Transformer 120VAC so will need to have a neutral wire.
0201-207004	*MSPA-MP-P122-P222-B1-O1-CP1-NE-LS-H4.0-T2-FB-AMP-PPD	0201-300014	
0201-207005	*MSPA-MP-P122-P222-B1-O1-CP1-NE-LS-H4.0-T2-FB-JJC-PPD	0201-300014	
0201-209001	**MSPA-MP-P122-P222-P312-B2-O1-CP1-NE-LS-HVS-IR-JJM-SA1	0201-300014	Change overlay for 9916-100130 / Kinetic lightning not available anymore / No more summer set mode / Functionalities different.
0201-209004	**MSPA-MP-P122-P222-BH1-O1-CP2-NE-LS-HB-RTC-IR-FB1-JJM-LA1	0201-300014	Blower heater not supported anymore.
0201-209005	**MSPA-MP-P122-P212-B2-O1-CP2-A11-LS-H4.0-IR-RL-JJM-SR1	0201-300014	

0201-209006	*//MSPA-MP-P122-P222-BH1-O1-CP2-NE-LS-HB-IR-FB1-JJC-LA2	0201-300014	If using a model 2500 keypad, change the overlay for a 9916-100130 / No more blower heater.
0201-209007	**MSPA-MP-P122-P212-P312-O1-CP1-NE-L1-HVS-FB1-RTC-LS-JJM-MA1	0201-300014	If using a platinum series keypad, will need to replace it with BDLTSC410K
0201-209008	**MSPA-MP-P122-P222-B2-O1-CP2-LS-HVS-IR-JJM-MB1	0201-300014	
0201-209009	**MSPA-MP-P122-P222-B1-O1-CP1-L2K-HP-IR-JJM-BF1	0201-300031	
0201-209010	**MSPA-MP-P122-P222-P311-B2-O1-CP2-A11-A21-NE-LS-H5.5-RTC-NF-JJM-DY1	0201-300014	If system equipped with 3 pumps and blower, pump 3 and blower will be controlled by the blower switch
0201-209012	**MSPA-MP-P122-P222-B1-O1-NE-A11-A21-LS-H5.5-IR-JJM-SU2	0201-300014	
0201-209013	**MSPA-MP-P122-P222-B1-O1-NE-LS-H5.5-IR-JJM-SU1	0201-300014	
0201-209014	**MSPA-MP-P122-P222-B2-O1-NE-A11-A21-LS-H5.5-T2-AMP-RL-SB1	0201-300014	
0201-209015	MSPA-MP-P122-P222-P312-B1-O1-CP1-NE-A11-A21-LS-H5.5-RTC-IR-SPW-JJC-GE1	0201-300014	
0201-209016	**MSPA-MP-P112-P212-P312-P412-P512-O1-CP1-NE-LS-HLG-RTC-FB1-JJM-MA2	0201-300014	
0201-209017	*MSPA-MP-P122-P212-B1-O1-NE-LS-H5.5-IR-SPW-JJC-CA1	0201-300014	
0201-209019	*//MSPA-MP-P122-P212-P312-B2-O2-A11-A21-L2S-H5.5-RTC-IR-SPW-AU1-JJC-HI1	not replaceable	See Hydropool for replacement
0201-209020	**MSPA-MP-P122-P222-B2-O2-CP2-NE-LS-HP-IR-T2-AMP-AP1	0201-300014	
0201-209021	**MSPA-MP-P122-P212-B2-O1-NE-LS-H5.5-RTC-IR-RL-FB1-AU1-JJM-AX2	0201-300014	
0201-209022	**MSPA-MP-P122-P212-B2-O1-CP2-A11-NE-LS-H4.0-IR-RL-JJM-SR2	0201-300014	
0201-209023	**MSPA-MP-P122-P212-P312-O1-CP1-NE-HLG-FB1-RTC-LS-JJM-MA3	0201-300014	If using a platinum series keypad, will need to replace it with 0201-007044 and overlay 9916-100761.
0201-209024	**MSPA-MP-P122-P222-P312-B2-O1-CP1-NE-LS-HVS-IR-SPW-JJM-SA2	0201-300014	Change overlay for 9916-100130 / Kinetic lightning not available anymore / No more summer set mode / Functionalities different.
0201-209026	**MSPA-MP-P122-P212-BV1-O1-NE-LS-H5.5-IR-RTC-RL-FB1-AMP-OM	0201-300014	Need to change the overlay for 9916-100094 / Pump 1 and pump 2 now have their own keys / Blower not variable anymore / No quiet key anymore / Functionalities different.
0201-209027	****MSPA-MP-P122-P212-B2-O1-NE-LS-H5.5-IR-AU11-AU21-AMP-SL1	0201-300014	
0201-209031	**MSPA-MP-P122-P222-P311-B2-O2-CP2-A11-A21-NE-LS-H34.0-RTC-IR-NF-JJM-DY2	0201-300014	If system equipped with 3 pumps and blower, pump 3 and blower will be controlled by the blower switch
0201-209033	**MSPA-MP-P122-P212-P312-B1-O1-CP1-L2K-HP-IR-JJM-BF1	0201-300031	
0201-209035	**MSPA-MP-P122-P212-O1-CP1-NE-LS-HP-IR-JJC-HY1	0201-300014	
0201-209036	**MSPA-MP-P122-P222-B2-O2-CP2-NE-LS-HP-AMP-DK1	0201-300014	
0201-209039	**MSPA-MP-P122-P222-B2-O1-CP2-NE-A11-LS-H4.0-IR-RL-JJM-SR3	0201-300014	
0201-209042	MSPA-MP-P122-P212-P312-B1-O1-CP1-A11-L2S-HP-IR-JJC-BF3	0201-300031	
0201-209044	*MSPA-MP-P131-P231-BH1-A1-A2-L-HR-IR-AMP-AQ1	not replaceable	See Aquatic Industries for replacement

0201-209053	*MSPA-MP-P122-P212-P312-B2-O2-A11-A21-L2S-H4.0-RTC-IR-AU1-SPW-JJC-HI2	not replaceable	See Hydropool for replacement
0201-209056	*MSPA-MP-P122-P222-B2-01-CP2-NE-A11-LS-H4.0-AU1-IR-RL-JJC-SR4	0201-300014	
0201-209058	*MSPA-MP-P122-P212-B2-O1-NE-LS-H5.5-RTC-IR-SPW-RL-AU1-JJC-AX3	0201-300014	
0201-209059	*MSPA-MP-P122-P222-P312-B1-01-CP1-NE-A11-A21-LS-HLG5.6-RTC-IR-SPW-JJC-GE2	0201-300014	
0201-209061	*MSPA-MP-P122-P222-P312-B1-01-CP1-NE-A11-A21-LS-HR-RTC-IR-SPW-JJC-PA1	0201-300014	
0201-209069	*MSPA-MP-P122-P222-P312-B2-01-CP2-NE--LS-H4.0-IR-SPW-RL-AU11-JJC-SR5	0201-300014	Blower switch now controls pump 3.
0201-209070	*MSPA-MP-P122-P212-P312-B2-01-NE-LS-H5.5-RTC-IR-SPW-RL-AU1-JJC-AX4	0201-300014	Needs to change keypad if 3 pump system, change keypad for BDLTSC410K
0201-209074	*MC-MP-P122-P222-BH2-A12-A22- L-HR-IR-T2-AMP-AQ2	not replaceable	See Aquatic Industries for replacement
0201-209076	*MC-MP-P122-P212-P312-B1-01- CP1-L2S-HP-IR-AU11-JJC-BF5	0201-300031	
0201-209200	*MC-MP-P122-P212-P312-B2-01- NE-LS-H5.5-RTC-IR-SPW-RL-AU1-JJC-AX5	0201-300014	Needs to change keypad if 3 pump system, change keypad for BDLTSC410K
0201-209202	MC-MP-P122-P212-P312-01-CP1-A11-A22-LS-HLG5.5-RTC-IR-SPW-NF-JJC-D17	not replaceable	See D1 for replacement
0201-209203	//MC-MP-P122-P222-P312-B2-01-A11-A21-H5.5-RTC-IR-SPW-AU11-JJC-CC1	not replaceable	See Coast for replacement
0201-209204	MC-MP-P122-B2-O2-CP2-A12-A22-L-HR-IR-AU12-AMP-MA1	not replaceable	See Artesian for replacement
0201-300003	**BOARD & CABLE KIT MC-MP-BF1	0201-300031	
0201-300014	BOARD ASSY KIT MC-MP-GE	0201-300014	
0201-300015	**BOARD & CABLE KIT MC-MP-BF2	0201-300031	
0201-300019	**BOARD & CABLE KIT MC-MP-NE-AX3	0201-300014	
0201-300021	**BOARD & CABLE KIT MC-MP-NE-HI1	not replaceable	See Hydropool for replacement
0201-300024	**BOARD & CABLE KIT MC-MP-NE-HI2	not replaceable	See Hydropool for replacement
0201-300029	**BOARD & CABLE KIT MC-MP-MB1	0201-300014	
0201-300030	**BOARD & CABLE KIT MC-MP-AX4	0201-300014	Needs to change keypad if 3 pump system, change keypad for BDLTSC410K
0201-300032	**BOARD ASSY KIT MC-MP-LA2	0201-300014	If using a model 2500 keypad, change the overlay for a 9916-100130 / No more blower heater.
0201-300034	BOARD & CABLE KIT MC-MP-D16	not replaceable	See D1 for replacement
0201-300045	BOARD ASSY KIT MC-1-GE	0201-300045	
0201-300201	**BOARD + CABLE KIT MSPA-MP-SR5	0201-300014	
0201-300202	**BOARD + CABLE KIT MSPA-MP-AX5	0201-300014	Needs to change keypad if 3 pump system, change keypad for BDLTSC410K
3-64-7000	B-MC-MP-P12-P21-BV-0-NE AI-LS-RTC-IR-RL-FB-MG	0201-300014	Need to change the overlay for 9916-100094 / Blower not variable anymore / No quiet key anymore.
3-64-7001	B-MC-MP-P12-P22-O-CP-NE A1-L-RTC-SPW-NW-D11	not replaceable	See D1 for replacement
3-64-7002	*B-MC-MP-P12-P22-P31-B-O CP-NE-A1-LS-IR-SPW-PD1	0201-300014	Need to change the overlay for a 9916-100723 / No more safety light/radio switch.
3-64-7004	B-MC-CF5-P12-P22-B-O-NE-L-NW -HQ/33-0018-R6	not replaceable	See HQ for replacement
3-64-7005	*B-MC-CF5-P12-P22-B-O-NE-L-T2 T2-NW-HQ/33-0023-R3	not replaceable	See HQ for replacement
3-64-7007	B-MC-MP-P12-P21-P31-B-O-CP-NE A1-A2-L-HVS-RTC-SPW-NW-D14	not replaceable	See D1 for replacement
3-64-7010	B-MC-MP-P12-P22-P31-B-O-CP-NE LS-2LS-RTC-IR-HQ/33-0026-UR1	not replaceable	See HQ for replacement

3-64-7011	B-MC-MP-P12-P22-P31-B-O-CP-NE A1-A2-L-RTC-SPW-IR-HQ2	not replaceable	See HQ for replacement
3-64-7016	B-MC-MP-P12-P22-O-CP-NE-A1-L-RTC-SPW-NW-D17	not replaceable	See D1 for replacement
3-64-7017	B-MC-MP-P12-P22-O-CP-NE-A1-A2-L-RCT-SPW-NW-D18	not replaceable	See D1 for replacement
3-64-7012	B-MC-MP-P12-P22-O-CP-NE-A1-A2-L-RTC-SPW-NW-D15	not replaceable	See D1 for replacement
3-74-7005	MC-MP-P112-P212-P312-P412-P512-O1-CP1-NE-LS-HLG-RTC-FB1-JJM-MA2	0201-300014	
3-74-7006	MC-MP-P122-P212-P312-O1-CP1-NE-HLG-FB1-RTC-LS-JJM-MA3	0201-300014	If using a platinum series keypad, will need to replace it with 0201-007044 and overlay 9916-100761.
3-74-7007	MC-MP-P122-P222-B1-O1-NE A11-A21-LS-H5.5-IR-JJM-SU2	0201-300014	
3-74-7008	MC-MP-P122-P222-B1-O1-NE LS-H5.5-IR-JJM-SU1	0201-300014	
3-74-7009	MC-MP-P122-P222-B2-O1-NE A11-A21-LS-H5.5-T2-AMP-RL-SB1	0201-300014	
3-74-7011	MC-MP-P122-P222-P312-B2-O1-CP2-A11-A21-NE-LS-H34.0-RTC-IR-NF-JJC-DY2	0201-300014	If system equipped with 3 pumps and blower, pump 3 and blower will be controlled by the blower switch
3-74-7015	MC-MP-P122-P222-B2-O2-CP2-NE-LS-2LS-H5.5-RTC-IR-SPW-T2-JJM-RW1	0201-300014	
3-74-7017	MC-MP-P122-P212-P312-B2-O1-CP1-NE-LS-HP-IR-SPW-JJC-HY2	0201-300014	
3-74-7024	MC-MP-P122-P212-P312-O1-CP1-NE-A11-A22-LS-HLG5.5-RTC-IR-SPW-NF-FB1-JJC-D14	not replaceable	See D1 for replacement
3-74-7030	MC-MP-P122-P222-P312-B2-O1-CP1-NE-LS-HVS-IR-SPW-JJM-SA3	0201-300014	Change overlay for 9916-100130 / Kinetic lightning not available anymore / No more summer set mode / No more conserve mode / Fonctionnalités different.
3-74-7035	MC-MP-P122-P222-P312-B1-O1-CP1-NE-A11-A21-LS-H5.5-RTC-T2-AMP-SBD	0201-300014	
3-74-7036	MC-MP-P122-P222-P312-B1-O1-CP1-NE-A11-A21-LS-H5.5-RTC-T2-JJC-SBD	0201-300014	
3-74-7037	MC-MP-P122-P222-P312-B2-O1-CP2-A11-A21-NE-LS-H34-RTC-IR-SPW-NF-JJC-DY4	0201-300014	If system equipped with 3 pumps and blower, pump 3 and blower will be controlled by the blower switch
3-74-7041	MC-MP-P122-P222-B2-O2-CP2-NE-LS-HP-IR-T2-AMP-SPW-AP2	0201-300014	
3-74-7049	MC-MP-P122-P212-B2-O1-NE-LS-H4.0-RTC-IR-SPW-AU11-AMP-EM5	0201-300014	Board handles an internal fiber optic, no need for the EXM-5 / Functions on the keypad will not correspond with the overlay. Will need to change the keypad for a BDLTSC4GE1
3-74-7050	MC-MP-P112-P212-P312-P412-O2-CP2-NE-LS-HP-IR-SPW-T2-AMP-AP3	not replaceable	See with AP fro replacement
3-74-7052	MC-MP-P122-P222-P312-B1-O1-NE-LS-H5.5-IR-SPW-JJC-SU3	0201-300014	
3-74-7054	*MC-MP-P112-P212-P312-P412-P512-O1-CP2-NE-LS-HLG-RTC-FB1-JJM-MA5	0201-300014	
3-74-7066	MC-MP-P122-P212-P312-O1-CP1-A11-A22-LS-HLG5.5-RTC-IR-SPW-NF-FB1-JJC-D16	not replaceable	See D1 for replacement
3-74-7067	MC-MP-P122-P212-P312-B1-O1-CP1-NE-LS-HR-RTC-IR-AU11-JJC-LA3	0201-300014	
3-84-7000	**BOARD & CABLE KIT MC-MP-NE-HY2	0201-300014	
3-84-7002	**BOARD & CABLE KIT MC-MP-NE-MA1	0201-300014	If using a platinum series keypad, will need to replace it with BDLTSC410K
3-84-7004	**BOARD & CABLE KIT MC-MP-NE-MA3	0201-300014	If using a platinum series keypad, will need to replace it with BDLTSC410K
3-84-7006	**BOARD+CABLE KIT MSPA-MP-NE-SA3	0201-300014	Change overlay for 9916-100130 / Kinetic lightning not available anymore / No more summer set mode / No more conserve mode / Fonctionnalités different.

3-84-7015	**BOARD & CABLE KIT MC-MP-NE-RW1	0201-300014	
3-84-7016	**BOARD & CABLE KIT MC-MP-NE-EM3	not replaceable	See Emerald for replacement
3-84-7021	**BOARD & CABLE KIT MC-MP-HY3	0201-300014	
3-84-7026	//BOARD & CABLE KIT MC-MP-MA4	0201-300014	
0201-209072	BF4	0201-300031	